



STANDARDS BULLETIN No : S01-05-001

SUBJECT: LV-ABC Supplied with String

Background:

Power and Water was recently supplied LV-ABC in various sizes and configurations with a blue/red/white string surrounding the bundle for the entire length of the drums.



The manufacturer and supplier were contacted, who informed Standards Engineering that the string was used for internal factory processes and should have been removed prior to supply to Power and Water.

The string may pose a safety concern as it becomes loose and unravels in the wind, as such it is required to be removed prior to installation if encountered.

Actions:

1. Inventory have organised the drums of all affected LV-ABC to be re-rolled with the string removed at cost to the manufacturer.
2. Standards Engineering is engaged with the manufacturer to reassess quality assurance processes.